



Special Tools for Repair

0.7 hp. Router

Model: 51863

Repair Tools:

50971 Lock Ring Tool (Base Plate)

96232 Arbor Press (#2)

96240 Bearing Press Tool (02649 Bearing)

96346 Bearing Separator (2")